PM Activities

				Shift	Group	trade	TMS /SMP Activity Number	Repeat Type	Repeat Value	Repeat On	Frequency Value	Activity Type	Activity Priority	Est Time	Est Time	last PM date	P/N/A	Status	Blockable	U/D	MEB6	Men Req	SMP File	If MC is the PM Repeat Type												Last Pm Count	Error Msg	READING DESCRIPTION	Seq	LOW READING	HIGH READING	UOM	NPM CODE	NPM Count	NPM P/S	Blank	2 Error(s)
	Blank	TMS Equipment	TMS Extension			Electrical, Mechanical, or Tool/Die	Same As SMP Number	See Example	How often to do PM based on Repeat type		Based on FC or VC type Activities (Counts/Cycles)			HH	:MM			A/I	Y/N	Dynamic - U Static - D			File Location	JAN	FEB	MAR	APR	MAY	JUN	JLY	AUG	SEP	OCT	NOV	DEC	Freq Value		If required	If required	If required	If required					
		Vendor	Vendor	Vendor for Daily Plant for others	Plant	Vendor	Vendor	Vendor	Vendor	Plant	Vendor	Vendor	Plant	Vendor	Vendor	Plant	Plant	Plant	Plant	Vendor	Plant	Vendor	Plant / MP&C	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Vendor	Plant		Vendor	Vendor	Vendor	Vendor	Vendor	Vendor				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	
1		FIN3 2075 PM01	DRIVE			Mechanical	520560	MC	1			PREVENTATIVE MAINTENANCE	STD	0	10					D			Drive Motor Assembly Inspection	1	1	1	1	1	1	1	1	1	1	1	1											
2		FIN3 2075 PM01	DRIVE			Mechanical	520570	MC	6			PREVENTATIVE MAINTENANCE	STD	0	30					D			Drive Motor Oil Change							1													47-100-6461	1			
3		FIN3 2075 PM01	DRIVE			Mechanical	520580	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Cardan Shaft Replacement																							
4		FIN3 2075 PM01	CN			Mechanical	520590	MC	3			PREVENTATIVE MAINTENANCE	STD	0	15					D			Tail Section Inspection			1			1			1			1										
5		FIN3 2075 PM01	CN			Mechanical	520600	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Linear Bearing Block Replacement																							
6		FIN3 2075 PM01	CN			Mechanical	520610	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Pillow Block Bearing Replacement																				04832A129	1			
7		FIN3 2075 PM01	CN			Mechanical	520620	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Wire Rope Replacement																							
8		FIN3 2075 PM01	CN			Electrical	568120	As Needed				PREVENTATIVE MAINTENANCE	STD	0	15					D			Replace Allen Bradley 802T-HP Limit Switch																				222076118	1			
9		FIN3 2075 PM01	CN			Mechanical	520630	MC	3			PREVENTATIVE MAINTENANCE	STD	0	15					D			Head Section Inspection			1			1			1			1										
10		FIN3 2075 PM01	CN			Mechanical	520640	As Needed				PREVENTATIVE MAINTENANCE	STD	0	45					D			Tail Section Pillow Block Bearing Replacement																				04832A129	1			
11		FIN3 2075 PM01	CN			Electrical	520650	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 842E Absolute Encoder Replacement																				222020571	1			
12		FIN3 2075 PM01	CN			Mechanical	520660	MC	3			PREVENTATIVE MAINTENANCE	STD	0	10					D			Mid Section Inspection			1			1			1			1										
13		FIN3 2075 PM01	CN			Mechanical	520670	MC	1			PREVENTATIVE MAINTENANCE	STD	0	15					D			Rexnord Plastic Belt Inspection	1	1	1	1	1	1	1	1	1	1	1	1											
14		FIN3 2075 PM01	CN			Mechanical	520680	As Needed				PREVENTATIVE MAINTENANCE	STD	0	60					D			Rexnord Chain and Sprocket Replacement																							
15		FIN3 2075 PM01	CN			Mechanical	520690	YR	1			PREVENTATIVE MAINTENANCE	STD	0	45					D			Rexnard Chain and Sprocket Inspection	1																						
16		FIN3 2075 PM02	DRIVE			Mechanical	520550	MC	1			PREVENTATIVE MAINTENANCE	STD	0	10					D			Drive Motor Assembly Inspection	1	1	1	1	1	1	1	1	1	1	1	1											
17		FIN3 2075 PM02	DRIVE			Mechanical	520570	MC	6			PREVENTATIVE MAINTENANCE	STD	0	20					D			Drive Motor Oil Change							1												47-100-6461	1			
18		FIN3 2075 PM02	DRIVE			Mechanical	520580	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Cardan Shaft Replacement																							
19		FIN3 2075 PM02	CN			Mechanical	520590	MC	3			PREVENTATIVE MAINTENANCE	STD	0	15					D			Tail Section Inspection			1			1			1			1										
20		FIN3 2075 PM02	CN			Mechanical	520600	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Linear Bearing Block Replacement																							
21		FIN3 2075 PM02	CN			Mechanical	520610	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Pillow Block Bearing Replacement																				04832A129	1			
22		FIN3 2075 PM02	CN			Mechanical	520620	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Tail Section Wire Rope Replacement																							
23		FIN3 2075 PM02	CN			Electrical	568120	As Needed				PREVENTATIVE MAINTENANCE	STD	0	15					D			Replace Allen Bradley 802T-HP Limit Switch																				222076118	1			
24		FIN3 2075 PM02	CN			Mechanical	520630	MC	3			PREVENTATIVE MAINTENANCE	STD	0	15					D			Head Section Inspection			1			1			1			1										
25		FIN3 2075 PM02	CN			Mechanical	520640	As Needed				PREVENTATIVE MAINTENANCE	STD	0	45					D			Tail Section Pillow Block Bearing Replacement																				04832A129	1			
26		FIN3 2075 PM02	CN			Electrical	520650	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 842E Absolute Encoder Replacement																				222020571	1			
27		FIN3 2075 PM02	CN			Mechanical	520660	MC	3			PREVENTATIVE MAINTENANCE	STD	0	10					D			Mid Section Inspection			1			1			1			1										
28		FIN3 2075 PM02	CN			Mechanical	520670	MC	1			PREVENTATIVE MAINTENANCE	STD	0	15					D			Rexnord Plastic Belt Inspection	1	1	1	1	1	1	1	1	1	1	1	1											
29		FIN3 2075 PM02	CN			Mechanical	520680	As Needed				PREVENTATIVE MAINTENANCE	STD	0	60					D			Rexnord Chain and Sprocket Replacement																							
30		FIN3 2075 PM02	CN			Mechanical	520690	YR	1			PREVENTATIVE MAINTENANCE	STD	0	45					D			Rexnard Chain and Sprocket Inspection	1																						
31		FIN3 2075 PMV01	AS			Electrical	520700	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 284E Armor Start Setting IP Address																				27-100-8025	1			
32		FIN3 2075 PMV01	AS			Electrical	520710	As Needed				PREVENTATIVE MAINTENANCE	STD	0	5					D			Allen Bradley 284E Armor Start Reset Failure																				27-100-8025	1			
33		FIN3 2075 PMV01	AS			Electrical	520720	As Needed				PREVENTATIVE MAINTENANCE	STD	0	5					D			Allen Bradley 284E Parameter Change																				27-100-8025	1			
34		FIN3 2075 PMV02	AS			Electrical	520700	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 284E Armor Start Setting IP Address																				27-100-8025	1			
35		FIN3 2075 PMV02	AS			Electrical	520710	As Needed				PREVENTATIVE MAINTENANCE	STD	0	5					D			Allen Bradley 284E Armor Start Reset Failure																				27-100-8025	1			
36		FIN3 2075 PMV02	AS			Electrical	520720	As Needed				PREVENTATIVE MAINTENANCE	STD	0	5					D			Allen Bradley 284E Parameter Change																				27-100-8025	1			
37		FIN3 SCB01	SAFB			Electrical	520730	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 1734-AENTR Communication Module Replacement																							
38		FIN3 SCB01	SAFB			Electrical	520730	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 1734-IB8S Safety Input Module Replacement																				24-200-4651	1			
39		FIN3 SCB01	SAFB			Electrical	520730	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 1734-OB8S Safety Output Module Replacement																				24-200-4652	1			
40		FIN3 SCB01	SAFB			Electrical	520730	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 1734-IB8 Input Module Replacement																				24-200-3774	1			
41		FIN3 SCB01	SAFB			Electrical	520740	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 1734-OB8E Output Module Replacement																							
42		FIN3 ENC1	EDON			Electrical	520650	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 842E Encoder Replacement																				22-207-0571	1			
43		FIN3 ENC2	EDON			Electrical	520650	As Needed				PREVENTATIVE MAINTENANCE	STD	0	30					D			Allen Bradley 842E Encoder Replacement																				22-207-0571	1			
44		FIN3 PSBX	PWRS																																												
45		FIN3 ESWX	ESW			Electrical	520780	As				PREVENTATIVE MAINTENANCE	STD	0	15					D			Hirschmann OS20 Ethernet Switch Replacement																							
46		FIN3 RRS01	CNPB																																												
47		FIN3 RRS02	CNPB																																												
48																																															
49																																															
50																																															